

KS-20489, L11, L12, L21, AND L22

RECTIFIERS

48 VOLTS, 400 AMPERES

TROUBLE LOCATING

1. GENERAL

1.001 This addendum supplements Section 169-741-311, Issue 2. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued to change AC INPUT CONTACTOR (ST2) to AC INPUT CONTACTOR (ST3) in Trouble Charts 5, 8, and 9. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 21, **TEST PROCEDURE B** (2), change (ST2) to (ST3).

2.002 On Page 34, **TEST PROCEDURE A** (1), change (ST2) to (ST3).

2.003 On Page 35, **TEST PROCEDURE C** (5), change (ST2) to (ST3).

2.004 On Page 36, **TEST PROCEDURE C** (8), change (ST2) to (ST3).

2.005 On Page 37, **TEST PROCEDURE C** (18), change (ST2) to (ST3).

2.006 On Page 43, **TEST PROCEDURE D** (5), change (ST2) to (ST3).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement