

MF SIGNALING-RECEIVING CIRCUIT SD-95536-01
ADJUSTING PROCEDURE
USING ADJUSTING CIRCUIT SD-95664-01

1. GENERAL

- 1.001** This addendum supplements Section 179-612-701, Issue 6.
- 1.002** This addendum is issued to revise Part 4, Test A Step 8, Test B Step 8, and Test D Step 11.

4. METHOD

The following changes apply to Part 4 of the section:

- (a) Test A, Step 8.
- (b) Test B, Step 8.
- (c) Test D, Step 11.

STEP	ACTION	VERIFICATION
A.		
8	Select the 12V ac scale on the KS-14510 L1 meter.	
B.		
8	Connect the - and + meter leads to the T and GND jacks, respectively, of the LEV test points.	
D.		
11	Connect ring (black conductor) to GND.	Meter indicates $45 \pm 5V$ dc.