



303-Type Connectors Description, Use, Installation, and Repair Procedures

1. Overview

- 1.001** This addendum supplements AT&T 201-208-108, Issue 1. Place this pink sheet ahead of Page 1 of the practice.
- 1.002** This addendum is issued to correct and clarify the procedures for removing, replacing and installing terminals.

2. Changes

Issue 1 Changes

- 2.001** On Page 15, replace paragraph 4.07 with the following:

The 840212476 terminal (solder-plated) and the 841634207 terminal (gold-plated) have been rated DA (Discontinued Availability) on all 303-type connectors and was replaced with the 842360562 (select gold-plated) terminal. The 842360562 terminal is rated LA (Limited Availability) and is replaced by the 846587285 terminal which has a gold-plated stripe inside the socket position.

- 2.002** On Page 16, replace paragraph 4.09 with the following:

To replace the 842360562 or 846587285 tip or ring terminal (Figure 8), proceed as follows:

- 2.003** On Page 16, replace paragraph 4.09, Step 2 with the following:

Using the fingers, push the terminal into the hole as far as possible, then use an orange stick to seat the terminal.

- 2.004** On Page 16, replace paragraph 4.09, Step 5 with the following:

Using the B long-nose pliers, carefully spread the legs or tangs of the terminal to lock the terminal in place in the connector panel.

2.005 On Page 16, replace paragraph 4.10 with the following:

To remove the 814648622 (P-46D862) or 846587335 ground terminal (Figure 8), proceed as follows:

2.006 On Page 16, add the following steps to paragraph 4.10:

- (3) To replace the 846587335
- (4) Follow the procedure outlined in paragraph 4.09, Steps (1) through (4).
- (5) Using the B long-nose pliers, fold the legs of the terminal around the ground rod.
- (6) Remove the protector unit.

2.007 On page 16, replace paragraph 4.12 with the following:

To remove the 842137986 or 846587386 test terminal (Figure 8), proceed as follows:

2.008 On Page 16, replace paragraph 4.13 with the following:

To replace the 842137986 or 846587386 test terminal, proceed as follows:

2.009 On Page 17, replace paragraph 4.14 with the following:

To remove the P-21E489 or 846587384 cross-connect terminal (Figure 8), proceed as follows:

2.010 On Page 17, replace paragraph 4.15 with the following:

To replace the P-21E489 or 846587384 cross-connect terminal, proceed as follows: