



## **305-Type Connectors Description, Use, Installation, and Repair Procedures**

### **1. Overview**

---

- 1.001** This addendum supplements AT&T 201-208-109, Issue 1. Place this pink sheet ahead of Page 1 of the practice.
- 1.002** This addendum is issued to show the discontinued availability of the 305-type connectors and show the recommended replacements, the 310- or 311-type connectors.

### **2. Changes**

---

#### **Issue 1 Changes**

---

- 2.001** On Page 2, Part 1, replace paragraph 1.01 with the following.
- 2.002** This practice covers the description, use, installation, and repair procedures for 305-type connectors. The 305-type connectors are rated DA (Discontinued Availability) effective June 1, 1992. Recommended replacements are the 310- or 311-type connectors.