

**CABLE PRESSURE TELEMETRY**  
**CENTRAL CONTROL**  
**TEST AND TROUBLE ANALYSIS PROCEDURES**

**1. GENERAL**

**1.001** This addendum supplements Section 201-610-501, Issue 2.

**1.002** This addendum is issued to add Test E.1. This issue affects the Equipment Test List.

The following change applies to Part 1 of the section:

- (a) 1.03—Test E.1, added

**1.03** (Add to the list of tests)

**E.1 Printer Ribbon Check:** This test checks that the ribbon is supplying the necessary ink for the printer. This test also checks for deterioration and fraying of the ribbon.

**3. METHOD**

The following changes apply to Part 3 of the section:

- (a) 3. METHOD (Add after Test E)

STEP	ACTION	VERIFICATION
<b>E. 1</b>	<b>Printer Ribbon Check</b>	
1	Inspect printed numbers for legibility.	Numbers shall be dark enough to insure legibility.
2	Remove the printer from the case and inspect the ribbon for signs of wear.	Ribbon shall not show signs of deterioration, especially fraying.  <b>Note:</b> Any sign of deterioration of the ribbon, especially fraying, is cause for replacement. This will prevent jamming of the print mechanism by the ribbon.
3a	If either requirement of Step 1 or 2 is not met— Refer to Section 201-610-311 for ribbon replacement.♦	