

COMMON SYSTEMS MESSAGE PRINTER SD-94865-01

DESCRIPTION, OPERATING PROCEDURES, AND MAINTENANCE

1. GENERAL

1.001 This addendum supplements Section 201-842-100, Issue 1. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued in compliance with the FCC ruling which requires a warning statement in the user's documentation for equipment that generates, uses, and can radiate radio frequency energy. This warning is required for all such equipment manufactured after January 1, 1981, that has not been tested to show compliance.

2. CHANGES TO SECTION

2.001 At the end of paragraph 1.01, add the following:

Warning: This equipment generates, uses, and can radiate radio frequency

energy and, if not installed and used in accordance with the instructions manual, may cause interference to radio communications. As temporarily permitted by regulation, it has not been tested for compliance with the limits for Class A computing devices pursuant to Subpart J of Part 15 of FCC Rules, which are designed to provide reasonable protection against such interference. Operation of this equipment in a residential area is likely to cause interference; in which case, the user, at his own expense, will be required to take whatever measures may be required to correct the interference.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.

Page 1
1 Page