

44

**AUTOMATIC INTERCEPT SYSTEM**  
**OUTGOING SENDER SD-27882-01**  
**TESTS USING OFFICE TEST FRAME SD-27633-01 (J23260)**  
**NO. 5 CROSSBAR OFFICES NOT ARRANGED FOR**  
**LINE LINK PULSING**

**1. GENERAL**

**1.001** This addendum supplements Section 218-457-502 Issue 2. Place this pink sheet ahead of Page 1 of the section.

**1.002** This addendum is issued to revise Test O to add a caution statement preceding Step 8 and to change the action statement of Step 9a.

**2. CHANGES TO SECTION**

**2.001** On Page 18 preceding Step 8 add the following:

***Caution: Any adjustment to the output frequency using the Berkley EPUT***

***or Hewlett-Packard frequency meter must be performed during periods of light traffic to avoid service interruptions.***

**2.002** On Page 18, revise Step 9a to read:

**If output frequency is not within limits as specified in Table B, refer to paragraph 1.05.**

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement