

**FEATURE DOCUMENT**  
**ANNOUNCEMENT ARRANGEMENTS**  
**NO. 2 ELECTRONIC SWITCHING SYSTEMS**

**1. GENERAL**

**1.001** This addendum supplements Section 232-190-023, Issue 1. Place this pink sheet ahead of Page 1 of the section.

**1.002** This addendum is issued to correct the functional flowchart associated with the

Vacant Code—No Such Number, 1+ Dialing Error, Custom Calling Error, and Intercept announcements.

**2. CHANGES TO SECTION**

**2.001** On Figure 4, under entry bubble A, interchange the boxes labeled PROCESS DISCONNECT and ADMINISTER PERMANENT SIGNAL TREATMENT TO CUSTOMER.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement