

CABLING METHODS  
SOLDERING

1. GENERAL

1.01 This addendum is issued to publish a change to Section 256-01 O-201, Issue 3.

1.02 In ink or red pencil, make the change indicated in Part 2 of this addendum. In the margin adjacent to the material affected write "See addendum." File this addendum in front of Section 256-010-201, Issue 3. Remove and destroy Issue 1 of Addendum 256-010-201.

2. CHANGES

2.01 Add a caution note under paragraph 3.01 to read as follows:

CAUTION: Soldering irons should be periodically inspected for proper isolation from ground and the ac line.