

DIMENSION[®] PBX
FEATURE TEST
MISCELLANEOUS TRUNK RESTRICTION TESTS

CONTENTS

1. GENERAL INFORMATION
 2. RECORDS AND REQUIREMENTS
 3. TEST EQUIPMENT
 4. PROCEDURE
-

1. GENERAL INFORMATION

1.1 Description

1.11 This section describes the tests to be performed whenever the Miscellaneous Trunk Group Restriction feature is utilized.

1.12 This feature restricts a station from accessing trunk groups and is dependent upon the line Class of Service and assignments of trunk groups with regards to the Miscellaneous Trunk Groups.

2. RECORDS AND REQUIREMENTS

2.1 Records

2.11 Form SD-97-1313 is required for recording the results of this test.

3. TEST EQUIPMENT

3.1 Handsets

<u>AMT</u>	<u>ITE</u>	<u>DESCRIPTION</u>
1	4208A	Telephone Handset

3.2 Cords

<u>AMT</u>	<u>ITE</u>	<u>DESCRIPTION</u>
1	9153 L	Cord Assembly

PRIVATE

THE INFORMATION CONTAINED HEREIN SHOULD NOT BE DISCLOSED TO UNAUTHORIZED PERSONS. IT IS MEANT SOLELY FOR USE BY AUTHORIZED BELL SYSTEM EMPLOYEES.

Printed in U.S.A.

4. PROCEDURE4.1 Test Procedure

- 4.11 From the Miscellaneous Trunk Restricted Group assignments section of the Customer Order Document determine the number of Miscellaneous Restricted Trunk Groups and the trunk group access codes assigned to each Miscellaneous Restricted Trunk Group.
- 4.12 Utilizing the MAAP panel and PROC 15¹⁷⁵ verify the trunk access code assignments determined in Step 4.11.
- 4.13 From the Class of Service and Station Line assignments section of the Customer Order Document pick a station with a Class of Service that is restricted from accessing the first Miscellaneous Restricted Trunk Group to be tested.
- 4.14 Utilizing the 249A Adapter connect the handset to the test line, at the circuit pack, associated with the station chosen in Step 4.13.
- 4.15 Go off-hook with the handset, verify dial tone, and then dial the first trunk access code associated with the first Miscellaneous Restricted Trunk Group to be tested. Verify:
- a) That Intercept Tone is received at the handset.
- 4.16 Go on-hook and repeat Step 4.15 until all trunk access codes associated with the Miscellaneous Restricted Trunk Group under test have been tested.
- 4.17 Repeat Steps 4.13 through 4.16 until all assigned Miscellaneous Restricted Trunk Groups have been tested.
- 4.18 This completes the testing of the Miscellaneous Restricted Trunk Group feature.

Manager, Denver PBX PECC