

E-TYPE REPEATERS

E6 REPEATER

This addendum is issued to correct information contained in Issue 1 of the section, as follows:

In Chapter II, Page II-5, Paragraph 5.03, change *491B disabling plug* to read *419B disabling plug*.

In Chapter V, Page V-6, left-hand column, second to last paragraph, change *491A head set plug* to read *419A head set plug*.

In Chapter V, Page V-9, right-hand column, Step (1), change *491B plug* to read *419B plug*.