

**DSX-1 AND DSX-1C PATCH AND CROSS-CONNECT BAY
RETROFITTING PROCEDURES
DIGITAL TRANSMISSION SYSTEMS**

1. General

1.001 This addendum supplements Section 365-301-301, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to change Steps 23 and 27 on Page 20, and to change a reference in Table A on Page 31.

2. CHANGES TO SECTION

2.001 On Page 20, change Step 23 to read as follows:

23 If retrofitting a D2 channel remove the -48V ALM fuse or if retrofitting a D3

channel bank remove the -48V ABS fuse from the power distribution panel.

2.002 On Page 20, change Step 27 to read as follows:

27 If retrofitting a D2 or a D3 channel bank, install the fuse removed in Step 23.

2.003 On Page 31 under Table A change Section 365-226-500 to read Section 365-800-003 (TOP).

**Reprinted to comply with modified final judgment.