

**OPERATION AND MAINTENANCE  
TERMINAL STATION  
1XN FREQUENCY DIVERSITY  
DR6/11-135A AND 135EC  
EXCESS ALARM**

**1. GENERAL**

**1.001** This addendum supplements AT&T 421-102-046, Issue 2, and replaces Addendum, Issue 1. Place this pink sheet ahead of Page 1 of the practice and discard Issue 1 of the addendum.

**1.002** This addendum is issued to delete reference to "AC" practices and to correct the note on Page 5.

**2. CHANGES**

**Issue 1 Changes**

**2.001** On Page 5, change Note 2 to read:

2. Patch cord should be 5 ft. or less. Select pads as follows:

- If interconnect cable to radio is 50 ft. long, use a 1.0-dB pad.
- If interconnect cable is longer than 50 ft., use a 10.6-dB pad and a 1.0-dB pad.

**Issue 2 Changes**

**2.002** On Page 1, delete all references to "AC" practices.