

**OPERATION AND MAINTENANCE  
1XN FREQUENCY DIVERSITY  
DR6/ 11-135A AND 135EC  
RADIO TRANSMITTER  
REPLACEMENT PROCEDURES**

**1. GENERAL**

1.001 This addendum supplements AT&T 421-102-061, Issue 3. Place this pink sheet ahead of Page 1 of the practice.

1.002 This addendum updates Page 2.

**2. CHANGES TO PRACTICE**

2.001 On Page 2, in the first paragraph, delete all references to "AC" practices.