

CLIMBING PRECAUTIONS

1. GENERAL

1.001 This addendum supplements Section 460-300-110, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is reissued to change the section numbers in Division 620 referred to in the section and in Issue 1 of this addendum.

1.003 Issue 1 of this addendum was issued to clarify whether or when a pole can be climbed if a B or C pole tag has been affixed to a pole.

2. CHANGES TO SECTION

ISSUE 1 CHANGES

2.001 On Page 1, revise paragraph 1.02 as follows:

1.02 Further tests required when hanging an aerial platform or riding strand in a cable

car are outlined in Sections 620-131-010 and 627-295-500. If the results of tests indicate poles must be temporarily supported, refer to Section 620-131-010.

ISSUE 2 CHANGES

2.002 On Page 5 add the following to paragraph 2.28:
It serves as a warning to craftspeople that the pole is defective and should **not** be climbed or worked on without following the recommendations of Section 620-131-010.

2.003 On Page 5 add the following to paragraph 2.29:
It serves as a warning to craftspeople that the pole is in a dangerous condition and should not be climbed or worked on before being temporarily supported as described in Section 620-131-010.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement