

KS-16161 TELETRAINER

1. GENERAL

1.001 This addendum supplements Section 473-410-100, Issue 1.

1.002 This addendum is issued to advise that the KS-16161 teletrainer has been rated manufacture discontinued (MD) and is replaced by the KS-16605 teletrainer.