

SERVICE
2554B, 2554BM, 2554BMP, AND 2554BMPG TELEPHONE SETS
CONNECTIONS

1. GENERAL

1.001 This addendum supplements Section 502-523-402, Issue 10. Place this pink sheet ahead of Page 1 of the Section.

1.002 This addendum is issued for the following reasons:

- (a) To change the rating of the 2554BMP telephone set to manufacture discontinued (MD).
- (b) To show 2554BMPG telephone sets manufactured after 6-1-82 will be marked (under or near the date code) "1-PTY". This marking indi-

cates that the set cannot be used for multiparty service connections or wired for A-lead control.

2. CHANGES TO SECTION

2.001 On Page 1, add paragraph 1.08 as follows:

1.08 The 2554BMPG telephone sets *not* marked "1-PTY" are adaptable for all classes of line and ringer connections and for A-lead control. The 2554BMPG telephone sets marked "1-PTY" cannot be used for multiparty service connections or wired for A-lead control; if service other than individual or bridge ringing is required, a 2554B2PG telephone set base, housing, and handset must be ordered separately.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement