

## KS-19425 BOOTH (INDOOR-OUTDOOR) MAINTENANCE

### 1. GENERAL

1.001 This addendum supplements Section 508-232-300, Issue 2.

1.002 This addendum is issued to:

- Add a replacement part to Table A.
- Delete information on bottom panels.

### 7. PANEL REPLACEMENT


The following changes apply to Part 7 of the section.

- (a) Table A, part no. added
- (b) 7.05 (part of paragraph deleted)

TABLE A

NAME	PART NO. OR DESCRIPTION	REMARKS
Bumper	B-684714	Used on left door frame

Delete



*The rear-bottom panels are equipped with a mounting bracket and leveling device. When ordering replacement panels for the rear, and a mounting bracket angle (B-684710) is not needed, the following numbers may be used.*

- KS-19580, List 49 — Solid Panel
- KS-19580, List 50 — Short Panel