

KS-16844 RAPIDIAL

IDENTIFICATION, INSTALLATION, OPERATION, CONNECTIONS, AND MAINTENANCE

1. GENERAL

1.001 This addendum supplements Section 512-115-100, Issue 4.

1.002 This addendum is issued to:

- Show repair parts no longer available for **Rapidial***
- Recommend that the **Rapidial** be replaced with **Magical**† dialer

* Registered trademark of McGraw-Edison Co.

† Registered trademark DASA Corporation.

6. MAINTENANCE

The following change applies to Part 6 of this section:

(a) 6.04.1—added

6.04.1 Repair parts for the KS-16844 **Rapidial** repertory dialer (MD) are no longer available. It is recommended that where **Rapidial** service can no longer be maintained the KS-19594 **Magical** dialer be substituted.