

KS-19245, LIST 1
TELEPHONE ANSWERING SET
MECHANICAL ADJUSTMENT AND MAINTENANCE

1. GENERAL

CHART A

1.001 This addendum supplements Section 514-155-300, Issue 1.

1.002 This addendum is issued to:

- Add a method of protecting the stenciling on front panel
- Add to and correct reference to miniature lamps available
- Add information on drive belt slippage.

The following changes apply to Part 1 of the section:

- (a) 104 added
- (b) Table A revised
- (c) Chart A, items 5 and 6 added

1.04 The stenciling on the front panel of KS-19245, List 1 telephone answering set may be protected from excessive wear by applying a coat of 639A flat clear lacquer or its equivalent.

Table A Page 10 revised

PARTS	ORDERING INFORMATION	REMARKS
Lamp miniature	No. 334-LSV* (Chicago Miniature Lamp Co.), GE #388*, or equivalent	IN-USE, AUTO-ANS and ON-OFF lamp bulbs

*25,000 Hour Life



Before proceeding with operational procedure make the visual inspection listed below.

VISUAL INSPECTION

5. Lamp Bulbs (IN-USE, AUTO-ANS and ON-OFF)

General Electric No. 334 Lamp (rated 1000 hours) should be replaced by General Electric No. 338 or Chicago Miniature No. 334-LSV Lamp (both rated 25,000 hours).

6. Drive Belt Slippage

Silicone oil from the drive motors creeps along the shafts and eventually over the pulleys until it reaches the belts. This causes the belts to stretch somewhat and also reduces the friction between the belts and the pulleys, both of which cause warble. Stretched belts work satisfactorily if they and the pulley surfaces are cleaned per 11.02.