

**TELEPHONE SETS—3666A1-TYPE**  
**IDENTIFICATION, INSTALLATION, OPERATION,**  
**CONNECTIONS, AND MAINTENANCE**

**1. GENERAL**

**1.001** This addendum supplements Section 529-236-133, Issue 2.

**1.002** This addendum is issued to add lamp replacement information for 635-type keys.

(d) The current production 635-type keys have been modified for easy lamp replacement by merely removing the lamp cap and inserting a 553-type tool through the hole in the top of the button. In early production keys it was necessary to remove faceplate, key collar, and button for lamp replacement.

**6. MAINTENANCE**

The following change applies to Part 6 of this section:

(a) 6 (d) added