

CallPilot

Installation and Configuration

Part 2: 200i Server Hardware Installation Addendum

Publication number:	P0987033
Product release:	2.0
Document release:	Standard 1.0
Date:	October 2002

ATTENTION

The 200i server has been replaced by the 201i server for customers ordering new CallPilot systems. As a result, the *Part 2: 200i Server Hardware Installation* guide is not being updated and released for CallPilot 2.0.

If you are upgrading your 200i server to CallPilot 2.0, refer to the following documentation for assistance:

- *Part 4: Software Installation and Maintenance* (NTP 555-7101-202) of the CallPilot 2.0 *200i Installation and Configuration* binder. Part 4 provides the procedures for upgrading from CallPilot 1.07 to CallPilot 2.0.
- *Part 5: 200i Server Maintenance and Diagnostics* (NTP 555-7101-214) of the CallPilot 2.0 *200i Installation and Configuration* binder. Part 5 provides instructions for troubleshooting, using diagnostic utilities, and performing server hardware maintenance.
- *Part 2: 200i Server Hardware Installation* (NTP 555-7101-213, Standard 1.0, May 2000) of the **CallPilot 1.07** *200i Installation and Configuration* binder. You received this documentation with your CallPilot 1.07 shipment. This documentation can be applied to your CallPilot 2.0 200i system since there are no technical changes to the 200i server hardware. You can also retrieve this document from the Nortel Networks Partner Information Center web site at <http://www.my.nortelnetworks.com>.