

TP163146 MODIFICATION KIT AND TP90790 FLAT WASHERS

APPARATUS AFFECTED: 28L, 28S, 28T, 28Y, 28AA, 28AF, 28AK, 28AL, 28LB, 28LC, 28LD, 28LE, 28LF Typing Units.

OBJECT: To increase the margin of the universal contact bracket adjustment.

CHANGE: Two TP90790 flat washers are added between the TP163158 universal contact bracket and the TP153299 left-hand stuntbox bracket.

For location of parts, see Bulletin 1149B, page 3-93, change 11, and Specification 5804S.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: Not affected.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Not affected.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be changed. If units are associated with 83B2 switching systems, the addition of the washers will facilitate the adjustment of the universal contacts.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with TP90790 washers.