

**TP195109 STOP PLATE**

*APPARATUS AFFECTED:* All 28- and 35-Type Typing Units equipped with TP195109 Stop Plates. (Used on TP153322 Guide to reduce wear caused by function levers.)

*OBJECT:* To prevent jamming and breakage of TP153598 and TP153604 function pawls on units equipped with TP195109 stop plates.

*CHANGE:* The TP195109 stop plate is to be changed by increasing the depth of the slots from 0.338 inch to 0.388 inch and increasing the overall width of the plate from 0.468 inch to 0.531 inch.

For location of associated parts, see Bulletins 1149B, page 3-49, change 11, and 1187B, page 4-30, change 1.

*IDENTIFICATION:* See "CHANGE."

*INTERCHANGEABILITY:* New and old style stop plates are not fully interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change shall be made as soon as manufacturing conditions permit. This is expected to be about April, 1965.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Shall not be furnished after new style stop plates become available.

*APPLICATION TO APPARATUS IN THE FIELD:* New style stop plates should be used where required for proper operation. Old style stop plates should not be used on units equipped with TP153598 or TP153604 function pawls.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units equipped with a TP153598 and/or a TP153604 function pawl and stop plates shall be equipped with new style stop plates. Old style stop plates shall not be used with these function pawls.