

TP152573 RETAINER

APPARATUS AFFECTED: All 28 Typing Units; all 28 Sequence Selectors; all 35 Typing Units; TP152573 Retainer.

OBJECT: To improve the clamping action of the TP152573 retainer.

CHANGE: The 0.100-inch offset on the TP152573 retainer is decreased to a 0.065-inch offset. The hardness range is increased from Rockwell C40-46 to Rockwell C48-54.

The TP152573 retainer is shown in Bulletin 1149B; Section 573-115-800, issue 1, page 28; Bulletin 1160B, page 2-6, change 1; and in Bulletin 1187B, page 4-15, change 1.

IDENTIFICATION: The new style retainer has a bronze plate; the old style retainer has a black oxide finish. (Some older style retainers are nickel-plated.)

INTERCHANGEABILITY: New and old style parts are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is expected to go into effect in the first quarter of 1965.

W.E.CO. STOCK OF OLD STYLE PARTS: Shall not be furnished after new style parts become available.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style parts.