

TP3606 NUT ON TP150755 STUD

APPARATUS AFFECTED: 28-type Typing Units.

OBJECT: To eliminate possible interference between the present TP3598 nut on the TP150755 stud and the TP119652 retaining ring which mounts the TP170064 lever to the TP170054 plate.

CHANGE: The TP3598 nut (6-40 by 3/32 inch thick) used to mount the TP150755 stud to the TP-170079 arm has been changed to a TP3606 nut (6-40 by 1/16 inch thick).

The TP3598 nut, TP150755 stud, and TP170079 arm are shown in Section 573-115-800, issue 1, page 38. The TP119652 retaining ring, TP170064 lever, and TP170054 plate are shown in Section 573-115-800, issue 1, page 37.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style parts are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished for other applications.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units shall be equipped with new or old style parts unless disassembled in this area for other reasons.