

## **TP156740 SCREW**

*APPARATUS AFFECTED:* All 28 Perforator-Transmitter-Bases; all 35 Perforator-Transmitter-Bases.

*OBJECT:* To provide a screw with adequate thread engagement.

*CHANGE:* The TP151722 or TP151631 screw used to fasten the TP159955 drive link to the TP159954 adjusting link is replaced with a TP156740 screw.

The TP151722 or TP151631 screw is shown in Teletype Bulletins 1167B, page 2-28, change 6; 1172B, page 15, change 3; 1166B, page 2-19, change 5; 1169B, pages 2-16, change 7, and 3-32, change 6; 1187B, page 5-10, original.

*IDENTIFICATION:* The TP156740 screw is 7/32 inch long; the TP151631 screw is 5/16 inch long; the TP151722 screw is 3/16 inch long.

*INTERCHANGEABILITY:* New and old style screws are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Where desired, the new style parts may be incorporated.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units shall be equipped with new style parts.