

TP159656 PUNCH BLOCK ASSEMBLY
TP159657 GUIDE AND DIE ASSEMBLY

APPARATUS AFFECTED: 28A, 28B, 28D, 28E, 28F, 28G, 28G-1, 28H, 28J and 28J-1 Perforator-Transmitter-Bases; 28A, 28B, 28C, 28D, 28E, 28F, 28G, 28J and 28K Typing Reperforator Units; 28A, 28D through 28D-6, 28E, 28F, 28F-1, 28F-2 Reperforator-Transmitter Units; TP159656 Punch Block Assembly; TP159657 Guide and Die Assembly.

OBJECT: To provide more clearance for the TP156869 ribbon guide.

CHANGE: The TP156004 die plate (part of the TP 159656 or TP159657 assemblies) is modified by removing 0.031 inch of material from the side opposite the punch holes for a distance of approximately 1 inch.

The TP159656 or TP159657 assemblies are shown in Bulletins 1167B, page 2-40, change 6; 1169B, page 3-8, change 6; and 1172B, page 11, change 3. The TP156869 ribbon guide is shown in 1167B, page 2-9, change 6; and 1169B, page 3-16, change 6.

IDENTIFICATION: See "CHANGE". On new style parts, the longer portion adjacent to the projection is approximately 15/64 inch wide compared to 17/64-inch width of old style parts.

INTERCHANGEABILITY: New and old style parts are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change will be put into effect as soon as manufacturing conditions permit.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.