

TP151632, TP151732, AND TP153538 SCREWS

APPARATUS AFFECTED: All 28 Typing Reperforator Units; all 28 Reperforator-Transmitter Units; 28A, 28B, 28E, 28G, 28G-1, 28H, 28J, 28J-1, and 28K Perforator-Transmitter-Bases.

35A Typing Reperforator Unit and 35A, 35A-X3, 35B, 35D, and 35D-X3 Perforator-Transmitter-Bases.

TP193988, TP193989, TP193992, and TP193993 Slack Tape Modification Kits (50247S, issue 1).

OBJECT: To provide the proper length screw for mounting the upper leg of the TP193966 bracket with stud to the TP152400 selector mounting plate.

CHANGE: The TP151722 screw (6-40 by 3/16 hex.) listed in the following modification kits is replaced as follows:

<i>Modification Kit</i>	<i>New Screw</i>
TP193988	TP153538 (6-40 by 7/16 hex.)
TP193989 and TP193992	TP151632 (6-40 by 3/8 hex.)
TP193993	TP151732 (6-40 by 11/32 fl)

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style screws are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished for other applications.

APPLICATION TO APPARATUS IN THE FIELD: Old style screws giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units shall be equipped with new style screws.