

TP162850 HANDLE

APPARATUS AFFECTED: 28A, 28B, 28C, 28D, 28E, 28F, 28G, 28J, 28K, 28L, 28M Typing Reperforator Units 28LA, 28LA-1 Tape Typing Units; 28A, 28D, 28D-1, 28D-2, 28D-3, 28D-4, 28D-6, 28E, 28F, 28F-1, 28F-2 Reperforator-Transmitter Units; 28D, 28K Perforator-Transmitter Bases; TP179133 Modification Kit; TP162850 Handle.

OBJECT: To facilitate manufacture by using the same handle on all units.

CHANGE: 1. The TP162850 handle is modified by adding a 6-40 tapped hole.

2. The TP176445 handle (having the 6-40 tapped hole) is being canceled.

3. The TP176445 handle now furnished in the TP179133 blank delete modification kit is replaced by the TP162850 handle. This is a number change only since the modified TP162850 handle and the canceled TP176445 handle are identical.

The TP162850 handle is shown in Teletype Bulletin 1167B, page 2-17, change 6, and page 2-41, change 6. The TP179133 modification kit is covered in Specification 50,058S.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New style handles are interchangeable with old style handles.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: There is no advantage in using new style parts.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.