

## **TP163015 PINION**

*APPARATUS AFFECTED:* 28D, 28E, 28E-1, 28G-1, 28K, 28L Perforator-Transmitter-Bases; TP163015 Pinion.

*OBJECT:* To prevent a possible interference between the TP163015 pinion and the TP151640 or TP150026 shoe release lever.

*CHANGE:* The TP163015 pinion is modified by removing 1/32 inch of material from the width of the toothed portion on the hub side.

The TP163015 pinion is shown in Teletype Bulletins 1167B, page 2-26, change 7; and 1169B, page 2-2, change 8.

*IDENTIFICATION:* New style pinions have a toothed portion approximately 25/64 inch wide; old style pinions have a toothed portion approximately 27/64 inch wide.

*INTERCHANGEABILITY:* New style pinions are interchangeable with old style pinions.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style parts giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* All units shall be equipped with new style parts if an interference is encountered.