

TP160551 AND TP160552 SLIDE ARMS

APPARATUS AFFECTED: 28B, 28F, 28G, 28G-1, 28LA and 28LB Transmitter-Distributor Units.

OBJECT: To prevent possible interference between the TP160551 and TP160552 slide arms with the TP164468 bail in the switch plate mechanism.

Note: The 28B transmitter-distributor unit uses only the TP160552 slide arm.

CHANGE: The TP160551 rear slide arm and the TP160552 front slide arm have been modified by changing the location of the actuating extension. When the modified arms are mounted on the TP160545 guide post, the actuating extensions project from underneath the guide post instead of over the guide post.

The TP160551 and TP160552 slide arms are shown in Bulletin 1165B, page 2-5, change 4, and in Bulletin 1182B, page 1-7, original.

The TP160552 slide arm is shown in Bulletin 1171B, page 10, change 1.

IDENTIFICATION: New style TP160551 and TP160552 slide arms have an angular projection adjacent to the slot. Old style TP160551 and TP160552 slide arms have a straight projection adjacent to the slot.

INTERCHANGEABILITY: New and old style slide arms are individually interchangeable but it is recommended that they be changed in pairs.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Shall not be used.

APPLICATION TO APPARATUS IN THE FIELD: New style parts should be incorporated in all transmitter-distributor units where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All transmitter-distributor units shall be equipped with the new style parts if interference is noted or if parts are disassembled for other reasons.