

28 AND 35 MULTIMAGNET NONTYPING REPERFORATOR BASE
LUBRICATION

1. GENERAL

(a) 1.04 - Revised

1.001 This addendum supplements Section
573-144-701.

1.002 This addendum is issued to delete ref-
erence to TP195298 grease which is
not a Pacific Tel. standard.

1.04 The motor is received with the ball
bearings packed with grease, but they
shall be repacked with KS7471 grease each
time the motor is disassembled.

The following change applies to Part 1
of the section: