

TP181284 SPRING

APPARATUS AFFECTED: 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33B, 33C, 33C-1, 33C-2, 33C-3, 33C-4 Teletypewriter-Sets.

OBJECT: To provide improved selector clutch operation.

CHANGE: The TP181407 spring is replaced by the TP181284 spring.

The TP181407 spring is shown in Teletype Bulletin 1184B dated 3/63, page 2-8.

IDENTIFICATION: New style springs are 0.778 inch long and have a tension of 22 ounces when extended to 1 inch. Old style springs are 0.818 inch long and have a tension of 18 ounces when extended to 1 inch.

INTERCHANGEABILITY: New and old style springs are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished for other applications.

APPLICATION TO APPARATUS IN THE FIELD: Units giving satisfactory service need not be changed.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style springs.

AVAILABILITY: Now available.