

TP180598 TYPEWHEEL

APPARATUS AFFECTED: 33A, 33A-1, 33A-2, 33A-3, 33A-4, 33B, 33C, 33C-1, 33C-2, 33C-3, 33C-4, 33D, 33D-1, 33D-2, 33D-3, 33D-4, 33E, 33F, 33F-1, 33F-2, 33F-3, and 33F-4 Teletypewriter-Sets.

OBJECT: To standardize the type of typewheel used on all 33-Type Teletypewriter-Sets.

CHANGE: The TP180461 typewheel incorporating a slash through the letter (ϕ) has been replaced by a TP180598 typewheel incorporating a zero without a slash (0).

The TP180461 typewheel is shown in Bulletin 1184B, page 2-22, Change 3.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style typewheels are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about February, 1964.

W.E.CO. STOCK OF OLD STYLE PARTS: Shall not be used.

APPLICATION TO APPARATUS IN THE FIELD: The new style typewheel should be incorporated in all apparatus where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with the new style typewheel as soon as manufacturing conditions permit.

AVAILABILITY: Available in February 1964.