

TP181266 BUSHING

APPARATUS AFFECTED:

33A through 33F-4 Teletypewriter-Sets
35A, 35B Call Control Units
TP182695 Selector Magnet Driver Assembly

OBJECT: To facilitate manufacture.

CHANGE: The TP181266 bushing material is changed from a tan phenolic to a white molded nylon. The diameter of the flange is decreased from 5/16 inch to 1/4 inch and the length of the shank is reduced from 7/32 inch to 11/64 inch.

For location of parts, see Bulletin 1184B, page 3-7, change 3, and Bulletin 1187B, page 2-4, change 1.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style parts are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be used.

APPLICATION TO APPARATUS IN THE FIELD: There is no advantage in using new style parts.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.