

## **TP180040 CONTACT BLOCK AND TP180046 BAIL**

**APPARATUS AFFECTED:** 33A-1 to 33A-5, 33C-1 to 33C-5, 33D-1 to 33D-5, 33F-1 to 33F-5 Teletypewriter-Sets.

**OBJECT:** To make the TP180040 contact block and associated TP180046 bail (in the keyboard and contact block) applicable for 5- and 6-level as well as 8-level units.

**CHANGE:** The TP180040 contact block has been modified by providing 5 additional contact slots in addition to 10 existing contact slots.

The over-all length of the TP180046 bail associated with the TP180040 contact block has been increased from 2-17/64 inches to 2-25/64 inches.

The TP180040 block and TP180046 bail are shown in Bulletin 1184B, page 4-2, change 3.

**IDENTIFICATION:** See "CHANGE".

**INTERCHANGEABILITY:** New and old style TP180040 blocks and TP180046 bails are not individually interchangeable.

**CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:** This change is now in effect.

**W.E.CO. STOCK OF OLD STYLE PARTS:** Should not be furnished after new style parts become available.

**APPLICATION TO APPARATUS IN THE FIELD:** Old style parts giving satisfactory service need not be replaced.

**APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:** Units may be equipped with new or old style parts. If parts involved require replacement, the new style parts shall be used.