

**TP182247 SLEEVE W/PLATES**

*APPARATUS AFFECTED:* 33C-1 thru 33C-5, 33F-1 thru 33F-5 Teletypewriter-Sets.

*OBJECT:* To provide a more rigid assembly.

*CHANGE:* 1. The TP182820, TP182834 plates and TP182855 sleeve have been replaced by a TP182247 sleeve w/plates.

2. The two TP180767 retainer rings, used in the old style assembly, are discarded.

The TP182820 and TP182834 plates, the TP182855 sleeve and the TP180767 retainer rings are shown in Teletype Bulletin 1184B, page 5-3, change 3.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New style assemblies are interchangeable with old style parts.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* Old style parts may be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* Old style parts giving satisfactory service need not be replaced.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts.