

TP182983 PUNCH BLOCK ASSEMBLY

APPARATUS AFFECTED: 33C-1 to 33C-5, 33F-1 to 33F-5 Teletypewriter-Sets.

OBJECT: To facilitate manufacture.

CHANGE: The old style TP182948 punch block assembly (shown as TP182907 in Bulletin 1184B, page 5-4) is replaced by a new style TP182983 punch block assembly.

The new style TP182983 punch block assembly has electroformed nickel sleeves as punch pin guides which are molded into and supported by epoxy resin (black) as a part of the punch block assembly. The heads of the screws that clamp the die plate and punch holder together mount into the recessed holes of the die plate which are filled with epoxy after assembly.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style punch block assemblies are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change shall be incorporated as soon as manufacturing conditions permit. This is expected to be about August, 1964.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Old style punch block assemblies giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style punch block assemblies.