

**TP192013 CONNECTOR (PLUG), TP192014 CONNECTOR (RECEPTACLE)  
TP195616 SPRING LOCK BRACKETS AND TP194982 CONNECTOR CLIPS**

*APPARATUS AFFECTED:* 35B Electrical Service Unit, 35A Transmitter-Distributor Unit, 35A Transmitter-Distributor Mounting.

*OBJECT:* To facilitate disconnecting the electrical service unit from the transmitter-distributor unit.

*CHANGE:*

*35A Transmitter-Distributor Mounting:* The TP192134 posts, associated with the TP192113 plate with connector, are discarded.

*35B Electrical Service Unit:* The pins from the TP192113 plate w/connector are transferred to the TP192014 connector (receptacle).

*35A Transmitter-Distributor Unit:* The pins from the TP173579 connector (plug) are transferred to the TP192013 connector (plug), or the TP173579 connector may be modified by adding TP195616 spring lock brackets and TP194982 connector clips.

The TP192113 plate with connector and the TP192134 posts are shown in Bulletin 1187B, pages 3-5 and 8-11, original. The TP173579 connector (plug) is shown in 1187B, page 8-3, original. For the TP192013 and TP192014 connectors, see "IDENTIFICATION". For wiring, refer to Section 574-202-400, 6000WD-C2; Section 574-225-400, 5814WD, issue D; Section 574-226-400, 5822WD, issue H.

*IDENTIFICATION:* See "CHANGE". For the TP192014 connector, see 1187B, page 3-5, original. For the TP192013 connector, see 1187B, page 7-22, original.

*INTERCHANGEABILITY:* All connector plugs and receptacles are interchangeable, whether modified or not.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be used for other applications.

*APPLICATION TO APPARATUS IN THE FIELD:* Where desired, new style parts may be used.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units shall be equipped with new style parts.