

**TP193845 MOUNTING PLATE, TP195243 HEAT SINK PLATE,
TP181675 POWER TRANSISTOR, AND TP182630 CIRCUIT CARD**

APPARATUS AFFECTED: 35F Electrical Service Unit.

OBJECT: To incorporate a constant current selector magnet driver card and a transistor heat sink plate.

CHANGE:

- (a) The TP193439 resistor and associated mounting hardware are removed.
- (b) The TP193440 circuit card is replaced by the TP182630 circuit card.
- (c) The TP195243 heat sink plate and TP181675 power transistor and their associated mounting hardware are added.
- (d) The TP193845 mounting plate is redesigned to accommodate the heat sink assembly.

The following sections are modified to include the above changes:

574-200-400 (35 RO) 6040WD-B8, Page 2; 6040WD-C3, Iss. 3
574-201-400 (35 KSR) 6020WD-B10, Page 2; 6020WD-C4, Iss. 3
574-202-400 (35 ASR) 6000WD-B11, Page 2; 6000WD-C4, Iss. 4
574-226-400 (35 ESU) 7170WD, Iss. 1

Parts are shown in Bulletin 1188B, page 5-2, original.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New and old style electrical service units are interchangeable, but new and old style circuit cards are not.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: May be furnished for other applications.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be replaced.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: Units may be equipped with new or old style parts.