

TP162350 ROCKER BAIL ASSEMBLY

APPARATUS AFFECTED: 35A, 35B Tape Typing Unit.

OBJECT: To eliminate an interference between the function box and the peened head of the ribbon drive roller post of the rocker bail assembly when used on eight level equipment.

CHANGE: A counterbore is being added to the leg of the rocker bail to insure that the peened head of the ribbon drive roller post will be flush or underflush with the leg of the rocker bail.

The TP162350 rocker bail assembly is shown in Teletype Bulletin 1188B, page 2-3, dated December, 1962.

IDENTIFICATION: New style rocker bail assemblies have a 0.281 inch diameter by 0.015 deep counterbore behind the ribbon drive roller.

INTERCHANGEABILITY: New style rocker bail assemblies are interchangeable with old style rocker bail assemblies.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect for eight level units. Present stocks of old parts will be exhausted on five level units only.

W.E.CO. STOCK OF OLD PARTS: May be furnished.

APPLICATION TO APPARATUS IN THE FIELD: Old style parts giving satisfactory service need not be changed.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All eight level units shall be equipped with new style parts. Five level units may be equipped with new or old style parts.