

## **TP156313 AXIAL OUTPUT RACK**

*APPARATUS AFFECTED:* 35A Typing Reperforator Unit; 35A, 35B Tape Typing Units; 35B, 35D Perforator-Transmitter-Bases.

*OBJECT:* To facilitate manufacture.

*CHANGE:* A notch 0.040 inch wide and 0.025 inch deep is being added to the end of the TP156313 rack adjacent to the rack teeth.

The TP156313 axial output rack is shown in Teletype Bulletin 1188B, page 2-12, original.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New and old style racks are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change will be put into effect at the convenience of Teletype.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* There is no advantage in using new style parts.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts.