

**TP192850 CONTACT ASSEMBLY, TP193733 CONTACT COVER, AND
TP156126 BUSHING**

APPARATUS AFFECTED: 35A Typing Reperforator Unit; 35A, 35B Tape Typing Units; 35B, 35D Perforator-Transmitter-Bases.

OBJECT:

1. To provide an improved TP192850 contact assembly which is less subject to loosening due to cold flow of the plastic cover.
2. To eliminate a possible interference between the TP193733 contact cover and the typing unit on ASR sets.

CHANGE:

1. The TP193733 contact cover is modified by reducing the over-all length from 2-5/16 inches to 2-5/32 inches and by enlarging the two 3/32 inch holes to 5/32 inch.
2. The two TP71073 flat washers are replaced by two TP156126 bushings in the TP192850 contact assembly.
3. The TP193733 contact cover is added to the TP192850 contact assembly.

The TP192850 contact assembly is shown in Teletype Bulletin 1188B, page 2-13, original.

IDENTIFICATION: See "CHANGE".

INTERCHANGEABILITY: New style contact covers and bushings are interchangeable with old style covers.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is expected to be in effect by September, 1964.

W.E.CO. STOCK OF OLD STYLE PARTS: Should not be furnished after new style parts become available.

APPLICATION TO APPARATUS IN THE FIELD: Should be incorporated in all apparatus where required for proper operation.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style parts as soon as new style parts can be obtained from Teletype.