

## **TP155096 SELECTOR PLATE**

**APPARATUS AFFECTED:** 35A Typing Reperforator Unit; 35A, 35B, 35D Perforator-Transmitter-Bases; 35A, 35B Tape Typing Units; All 35 Typing Units.

**OBJECT:** To eliminate a possible interference between the heads of the TP151737 screws on the clutch and the portion of the selector plate which guides the stop arm bail.

**CHANGE:** The TP155096 selector plate will be modified by lengthening the offset in the shorter guide finger from 0.195 inch to 0.351 inch.

The TP155096 selector plate is shown in Teletype Bulletins 1188B, page 2-14, original, and 1187B, page 4-22, original.

**IDENTIFICATION:** See "CHANGE".

**INTERCHANGEABILITY:** New and old style plates are interchangeable.

**CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:** This change will be put into effect when present tools are replaced.

**W.E.CO. STOCK OF OLD STYLE PARTS:** Old style plates may be furnished.

**APPLICATION TO APPARATUS IN THE FIELD:** Old style parts giving satisfactory service need not be replaced.

**APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:** Units may be equipped with either new or old style parts.