

## **TP192877 GUIDE BUSHING**

*APPARATUS AFFECTED:* 35A Typing Reperforator Unit; 35A and 35B Tape Typing Units; TP192877 Guide Bushing.

*OBJECT:* To facilitate manufacture and factory adjustment.

*CHANGE:* The over-all thickness of the TP192877 guide bushing is reduced from 0.225 inch to 0.195 inch diameter, and the 0.395 inch diameter counterbore is eliminated.

The TP192877 guide bushing is shown in Teletype Bulletin 1188B, page 2-9, original.

*IDENTIFICATION:* See "CHANGE".

*INTERCHANGEABILITY:* New style and old style parts are interchangeable.

*CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE:* This change is now in effect.

*W.E.CO. STOCK OF OLD STYLE PARTS:* May be furnished.

*APPLICATION TO APPARATUS IN THE FIELD:* There is no advantage in using new style parts.

*APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS:* Units may be equipped with new or old style parts.