

TP170198 STOPARM

APPARATUS AFFECTED: 35A, 35B, 35E and 35F Typing Units; 35A Typing Reperforator Unit; 35A and 35B Tape Typing Units; and 35A Perforator-Transmitter-Base.

OBJECT: To reduce breakage in the U-shaped portion of the TP170198 stoparm.

CHANGE: The U-shaped portion of the TP170198 stoparm is carbonized.

The TP170198 stoparm is shown in Bulletins 1187B, pages 4-22 and 5-9, original, and 1188B, page 2-14, original.

IDENTIFICATION: The old style stoparm is nickel-plated and the new style stoparm has a black oxide finish.

INTERCHANGEABILITY: The new and old style stoparms are interchangeable.

CLASSIFICATION FOR APPARATUS FURNISHED BY TELETYPE: This change is now in effect.

W.E.CO. STOCK OF OLD STYLE PARTS: Should not be furnished.

APPLICATION TO APPARATUS IN THE FIELD: The new style stoparms should be incorporated in all apparatus where stoparm breakage has been encountered.

APPLICATION AT W.E.CO. DIST. HOUSE REPAIR SHOPS: All units shall be equipped with new style stoparms as soon as new style parts can be obtained from Teletype.