

INFORMATION SUPPLEMENT
PBX AIOD-A1
TROUBLE SHOOTING GUIDE

1. General

- 1.1 The F25TKA error in TABLE A is no longer sequence 2.
- 1.2 Add pin numbers to waveform channel designation location.
- 1.3 Change in 'B' channel pin location for WF10.
- 1.4 Change wording of explanation of WF22.

2. Instructions

- 2.1 Change the sequence number in TABLE A for a F25TKA error to sequence 1.
- 2.2 Change WF2, A channel location to read,
"A chan: 003 05D13-13(RDX)"
- 2.3 Change WF10, B channel location to read,
"B chan: 001 01C13-14"
- 2.4 Change the explanation for WF22 to read, "The pulser is used to open and close the ferreed. . ."

Manager, Product Engineering
Control Center