

FIRST CLASS MAIL

*NOTICE

Installation Engineering Handbook 59
Western Electric Company, Incorporated
Columbus Works

UIS Section 430
Dated: 01/13/83

URGENT INFORMATION SUPPLEMENT

COMMON SYSTEMS
RECORDED ANNOUNCEMENT FRAME

1. GENERAL

1.1 Correct a dbrn reading inadvertently marked - instead of plus.

2. INSTRUCTIONS

2.1 Change Paragraph 5.65 to read as follows:

5.65 On the CSRA frame, plug W1 cord between DSM 1000 Hz jack and 3A NMS jack. Verify a +64 dbrn 1000 Hz test signal.

Manager, Product Engineering
Control Center

Printed in U.S.A.

*NOT FOR USE OR DISCLOSURE OUTSIDE THE BELL SYSTEM
EXCEPT UNDER WRITTEN AGREEMENT
