

**DATA SETS 201A- AND 201B-LIST TYPE  
TRANSMITTER-RECEIVER  
INSTALLATION AND CONNECTIONS**

**1. GENERAL**

**1.001** This addendum supplements Section 592-011-202, Issue 3.

**1.002** This addendum is issued to correct Note 8(b) in Fig. 5.

**2. CHANGES TO SECTION**

**2.001** On Page 11/12, Fig. 5, change Note 8 (b) to read as follows:

(b) When the DAS coding is 804A6 or 804A8, series 6 or later:

(1) In DAS 804A, disconnect and tape the wire from wire wrap terminal 2 on the printed wiring board. Disconnect and tape the wire on TB1-35 on the option board. Cut and tape the wire on connector J1, pin 34.

(2) Add a strap between wire wrap terminals 2 and 50 on the printed wiring board. Add a strap between option board terminals TB1-35 and TB1-40.

(c) Mark the modified DAS 804A to show that it has been modified in accordance with Section 592-011-202, Fig. 5, Note 8.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement